



Spare parts list for REP1100INOX

Pozice	Obj.číslo	Popis	Počet ks
1	CWSP.004.01.007	switch	1
2	CWSP.022.02.002	Cable	1
3	CWSP065.08.03.004f	Corss Srew/ST3.9*30F	3
4	CWSP006.02.026	Handle	1
5	CWSP.007.06.004	pump case	1
6	CWSP066.08.001	rubble air outlet	1
7	CWSP031.01.002	steel ball/ć6	1
8	CWSP065.08.03.001F	srew/3.9*13	2
9	REP1100INOX.11	main housing	1
10	CWSP.065.05.03.504	srew/M4*12	6
11	CWSP.038.01.008	O-Ring/ć13×3.55	2
12	CWSP007.06.003	rear pump cover	1
13	CWSP039.01.004	cable sheath	1
14	CWSP039.01.006	cable sheath	1
15	CWSP043.02.001	cable button up	1
16	CWSP043.02.001	cable button up	1
17	REP1100INOX.05	capacitance	1
18	CWSP042.01.010	cable button up	1
19	CWSP065.08.03.010F	tapping screw/ST3.9×30.5-f	3
20	CWSP065.05.02.002	screw	1
21	CWSP097.06.003	washer	1
22	CWWG.0009	Cable	1
23	CWSP097.05.001	washer	1
24	CWSP015.02.001	insulate cover	1
25	CWSP003.05.001	rear motor cover	1
26	CWSP097.01.001	washer	1
27	CWSP099.01.002	bearing/6201Z	2
28	REP1100INOX.03	rotor	1
29	REP1100INOX.04	stator	1
30	REP1100INOX.16	front motor cover	1
31	CWSP048.02.001	reinforced seal/ć24×12×4.5	1
32	CWSP048.01.003	mechanical seal	1
33	CWSP030.07.001	clip/ć12-A	1
34	CWSP097.08.004	washer/ć16×8×1	1

35	REP1100INOX.02	impeller	1
36	CWSP063.06.103	tighten screw/M8	1
37	CWSP038.01.037	O-Ring/ϕ89×4.9	1
38	CWSP012.01.001	plate	1
39	CWSP065.08.03.505F	tapping screw/ST3.9×24-f	6
40	CWSP043.05.001	screw	1
41	CWSP017.01.006	location clip	1
42	CWSP038.05.025	washer	1
43	CWSP053.01.010	output	1
44	CWSP038.01.026	O-Ring/ϕ37.5×3	2
45	CWSP053.01.009	elbow	1
46	CWSP010.02.004	base	1
47	CWSP011.01.003	base plate	1
48	CWSP065.08.03.501	tapping screw/ST3.9×13-F	3
49	CWSP100.01.003	screw	5
50	CWSP072.01.001	ribbon	1